

Elevated Mobile Repair, LLC.

1364 GRASSLAND ROAD
DAYTON, NV. 89403
(530) 329-6653



QUOTE # 166

elevatedmobilerepair@gmail.com
elevatedmobilerepair.com
Quote Date: 6/8/2026
Date Printed: 9/14/2026

INDEPENDENCE VOLUNTEER FIRE DEPT.,
PO BOX B
INDEPENDENCE, CA. 93526
Phone: 7609201108

2020 FORD F-250
1FT7W2B66LEC73493

1.BED SLIDE AND COMMAND CONSOLE

PART : MAKMGCHERM	REMOTE CONTROL HEAD, KAA0660 - PLUG AND PLAY KIT, INCLUDES KAA0638 FOR RELM BK RADIO KNG M	2 @ \$1,799.46	\$3,598.92
PART : XS3	DRAWER SYSTEM	1 @ \$2,209.99	\$2,209.99
PART : DCG1500-7348	CARGOGLIDE FOR DRAWER SYSTEM	1 @ \$1,949.99	\$1,949.99
PART : C0090-DCGBK-BLK 1	CARGOGLIDE MOUNTING BRACKETS FOR DRAWER SYSTEM	1 @ \$130.00	\$130.00
PART : CMD1	COMMAND BOX	1 @ \$1,560.00	\$1,560.00
LABOR :	INSTALL BED DRAWER SYSTEM, CARGO SLIDE, COMMAND BOX AND RADIOS.	24 hours	\$3,600.00

Total for BED SLIDE AND COMMAND CONSOLE: \$13,048.90

Disclosure: THANK YOU FOR THE OPPORTUNITY TO EARN YOUR BUSINESS. PLEASE NOTE THAT ALL PRICES, LABOR RATES AND LABOR TIMES ARE ACCURATE AS OF THE DATE OF THIS QUOTE, BUT ARE SUBJECT TO CHANGE.

Labor	\$3,600.00
Parts	\$9,448.90
Sublet	\$0.00
Subtotal	\$13,048.90
Fees	\$60.00
Tax	\$732.29
Total	\$13,841.19

5650 operating

2026 LOCAL AGENCY BIENNIAL REPORT

Government Code Section 87306.5 requires local agencies to submit to their code reviewing body a biennial report identifying changes in its code, or a statement that their code is not in need of amendment. Such reports shall be submitted to the Office of County Counsel for approval no later than October 1, of each even-numbered year. Once reviewed, the Office of County Counsel will submit all reports to the Board for their approval. You may use this form, or you may prepare your own report. When completed, all reports must be mailed to:

County Counsel – County of Inyo
PO Drawer M
Independence, California 93526

Email: mwatterson@inyocounty.us

This agency has reviewed its conflict-of-interest code and has determined that:

- (1) ☒ Our agency's code accurately designates all positions which make or participate in the making of governmental decisions; that the disclosure assigned those positions accurately requires the disclosure of all investments, business positions, interests in real property and sources of income which may foreseeably be affected materially by the decisions made by those designated positions; and further that the code includes all other provisions required by Government Code Section 87302; or,
- (2) ☐ Our agency's code is in need of amendment. We have determined that the following amendments are necessary (check applicable items):
- ☐ Include new positions which must be designated.
 - ☐ Make changes to the reportable sources of income, investments, business positions, or real property.
 - ☐ Make changes to the titles of positions assigned.
 - ☐ Delete positions which have been abolished or changed.
 - ☐ Change or add the provisions required by Government Code Section 87302.

Contact Person Janis L. Odum, Secretary
Agency Independence FireProtection District
Mailing Address P.O. Drawer B, Independence, CA 93526
Date of Review of Agency's Conflict of Interest Code _____

Signature of Presiding Officer

Note: Government Code Section 87306 requires that when a department has determined that amendments are necessitated by changed circumstances, the amendments or revisions shall be submitted to the code reviewing body within 90 days.

03182026

CONFLICT OF INTEREST CODE OF THE
Independence FireProtection
COUNTY OF INYO, STATE OF CALIFORNIA **DISTRICT**

SECTION 1. Purpose.

Pursuant to California Government Code section 87300, et seq., the Independence FireProtection District hereby adopts the following Conflict of Interest Code. Nothing contained herein is intended to modify or abridge the provisions of the Political Reform Act of 1974 (Government Code section 81000). The provisions of this Conflict of Interest Code are additional to California Government Code section 87100 and other laws pertaining to conflicts of interest. Except as otherwise indicated, the definitions of said Act and regulations adopted pursuant thereto are incorporated herein and this Conflict of Interest Code shall be interpreted in a manner consistent therewith.

SECTION 2. Designated Positions.

The positions listed on Appendix "A" are designated positions. Persons holding these designated positions are deemed to make, or participate in the making of, decisions which may have a material effect on a financial interest.

SECTION 3. Disclosure Statements.

Each designated position is assigned to one or more of the disclosure categories set forth in Appendix "B". Each person in a designated position shall file a statement of financial interest disclosing that person's interest in investments, business positions, real property, and income, designated as reportable under the disclosure category to which the person's position is assigned by Appendix "A".

Notwithstanding the disclosure category to which a consultant position is assigned by Appendix "A", the Presiding Officer of the Independence FireProtection District's Governing Board may determine in writing that a particular consultant, although a "designated" position, is hired to perform a range of duties that are limited in scope and, thus, is not required to fully comply with the disclosure requirements of the category designated for consultants on Appendix "A". Such written determination shall include a description of the consultant's duties and based upon that description, a statement of the extent, if any, of the disclosure requirements for such consultant. Such written determination is a public record and shall be filed and retained for public inspection in the same manner and locations as is required for statements of financial interest.

SECTION 4. Place, Time and Requirements of Filing.

(A) Place of Filing.

All persons required to file a statement of financial interests shall file the original with the Inyo County Clerk, and a copy with the Presiding Officer of the Independence Fire Protection District's Governing Board.

(B) Time and Content of Filing.

The first statement by a person in a designated position upon the effective date of this Conflict of Interest Code, shall be filed within thirty (30) days after the effective date of this Conflict of Interest Code, and shall disclose investments, business positions, and interest in real property, held on the effective date of this Conflict of Interest Code, and income received twelve (12) months before the effective date of this Conflict of Interest Code. The first statement by a person who assumes a designated position after the effective date of this Conflict of Interest Code, shall be filed within thirty (30) days after assuming such position with the District and shall disclose investments, business positions, and interests in real property held, and income received, during the twelve (12) months before the date of assuming such position. After filing the first

statement, each person in a designated position shall file an annual statement on or before April 1, disclosing reportable investments, business positions, interests in real property held, and income received, any time during the previous calendar year or since the date the person assumed the designated position during the calendar year. Every person in a designated position who leaves a designated position shall file, within thirty (30) days of leaving the position, a statement disclosing reportable investments, business positions, interests in real property held, and income received, at any time during the period between the closing date of the last statement required to be filed, and the date of leaving the position.

SECTION 5. Contents of Disclosure Statement.

Statements of financial interest shall be made on forms supplied by the Inyo County Clerk and shall contain all of the information as required by the current provisions of Government Code sections 87206 and 87207 for interest in investments, business positions, real property, and sources of income designated as reportable under the disclosure category to which the person's position is assigned on Appendix "A".

SECTION 6. Disqualification.

A person in a designated position must disqualify himself or herself from making, or participating in the making, or using their official position to influence the making of any decision which will have a material financial effect, as distinguishable from its effect on the public generally, on any financial interest as defined in Section 87103 of the Government Code. No person in a designated position shall be required to disqualify himself or herself with respect to any matter which could not be legally acted upon or decided without his or her participation.

APPENDIX "A"
CONFLICT OF INTEREST CODE OF THE
Independence FireProtection DISTRICT
COUNTY OF INYO, STATE OF CALIFORNIA

DESIGNATED POSITIONS

Designated Positions

Disclosure Category

Designated Positions named in Exhibit "A" are assigned to all of the following disclosure categories.

1. Ownership of, or control over all real property in excess of \$1,000 located in the district or within two miles of the Boundaries of the district, with the exception of officials' Principal residence.

2. Any financial interest, directly or indirectly, in any commercial firm with which the Fire Protection District might have dealings. This would include, but not limited to, automotive parts and supplies, mechanical services, Fire & Rescue equipment, petroleum products, building repair and maintenance services.

APPENDIX "B"

CONFLICT OF INTEREST CODE OF THE
Independence FireProtection DISTRICT
COUNTY OF INYO, STATE OF CALIFORNIA

DISCLOSURE CATEGORIES

Elected Commissioners

Appendix "B"

Appointed Secretary

Appendix "B"

Fire Chief

Appendix "B"

Assistant Fire Chief

Appendix "B"

Elevated Mobile Repair, LLC.

1364 GRASSLAND ROAD
DAYTON, NV. 89403
(530) 329-6653



INVOICE # 1349

elevatedmobilerepair@gmail.com
elevatedmobilerepair.com
BAR# 3216900

INDEPENDENCE VOLUNTEER FIRE DEP	YEAR:	2010	/:	A/4X4
PO BOX B	MAKE/MODEL:	FORD F-550	LICENSE/STATE:	1454538/CA
INDEPENDENCE, CA. 93526	VIN:	1FDOW5HT1BEB16030	MILES IN/MILES OUT:	22343/22343
Cell: (760) 920-1108 Work: (760) 878-2113	ENGINE:	6.7 POWERSTROKE	FLEET NUMBER	2228

PART: 43017	BATTERY TERMINAL	5 @ \$4.01	\$20.05	NEW
PART: DUAL-USB-C-HARN	MOB ARMOR DUAL USB CHARGER PORT	3 @ \$29.99	\$89.97	NEW
LABOR: TRAYLOR,	INSTALL AND FABRICATE CENTER COMMAND CONSOLE, WIRE IN AUX POWER PORTS AND RADIOS	27 @ \$150.00	\$4,050.00	LABOR
Total for "INSTALL CENTER COMMAND CONSOLE": \$6,442.66				
SHOP SUPPLIES : \$25.00				
HAZARDOUS WASTE : \$20.00				

See page 2 for date of service

Recommended Repairs: Warranty: From the date of delivery for a period of 3 months or 3000 miles, whichever comes first, this firm will repair free of charge any defects in material and workmanship to the repairs stated on the invoice. All work to be done in our shop only. This does not include towing charges or customer supplied parts. A storage fee of 0.00 per day will be charged 24 hours after notification that work is complete. Neglect/abuse of vehicle will immediately void any and all warranties.	Labor/Jobs	\$4,050.00
	Parts	\$2,392.66
	Sublet	\$0.00
	Total Fees	\$45.00
	Subtotal	\$6,487.66
	Tax @ 7.75%	\$185.43
	Total	\$6,673.09
	Payments	\$0.00
	Balance	\$6,673.09

Replaced parts may be requested by customer. I hereby authorize the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I have read the above and acknowledge receipt of an estimate.

X _____ Date 1/15/2026

VO07605

Wildland

Elevated Mobile Repair, LLC.

1364 GRASSLAND ROAD
DAYTON, NV. 89403
(530) 329-6653**INVOICE # 1349**elevatedmobilerepair@gmail.com
elevatedmobilerepair.com
BAR# 3216900

INDEPENDENCE VOLUNTEER FIRE DEP	YEAR:	2010	/:	A/4X4
PO BOX B	MAKE/MODEL:	FORD F-550	LICENSE/STATE:	1454538/CA
INDEPENDENCE, CA. 93526	VIN:	1FDOW5HT1BEB16030	MILES IN/MILES OUT:	22343/22343
Cell: (760) 920-1108 Work: (760) 878-2113	ENGINE:	6.7 POWERSTROKE	FLEET NUMBER	2228

In: 12/17/2025 Out: 1/15/2026 Email: IVFDJOE@GMAIL.COM

VEHICLE ISSUE #1: INSTALL CENTER COMMAND CONSOLE

TECH REPORT: CUSTOMER WANTS MIDDLE SEAT REMOVED AND COMMAND CONSOLE INSTALLED WITH CUSTOMER SUPPLIED NEW BK RADIO, HT CHARGERS AND THERMAL CAMERA. REMOVED CENTER SEAT AND ALL WIRING FROM EXISTING RADIO AND SIREN CONTROL. MADE CUSTOM WIRE HARNESS AND INSTALLED FROM HOOD TO BATTERY SWITCH WITH A 80 AMP CIRCUIT BREAKER NEXT TO BATTERY SWITCH. INSTALLED NEW ANTENNA AND CABLE WITH NEW BK CONNECTOR UNDER HEADLINER AND DRIVER SIDE A PILLAR. FABRICATED TROY BOX CONSOLE FLOOR MOUNTS AND SIREN FACE PLATE. INSTALLED FUSE BLOCK IN CONSOLE FOR ALL ACCESSORIES, MOUNTED BK SPEAKER, BK RADIO AND SIREN CONTROLLER. LOCATED AND MOUNTED FLASHLIGHT, HT CHARGERS, USB PORTS AND THERMAL CAMERA. INSTALLED FACEPLATES AND WIRED ALL ACCESSORIES TO FUSE BLOCK TESTED RADIO AND ACCESSORIES FOR PROPER OPERATION. TESTED OK.

PART: CC-MC-22	TROY, UNIVERSAL TALL-PROFILE MC CONSOLE	1 @ \$715.50	\$715.50	NEW
PART: AC-F150-15-MNT	TROY, CONSOLE FLOOR PLATE W/ FOOT BRACKETS, 2016-23 F150-550	1 @ \$238.50	\$238.50	NEW
PART: AC-INBHG	TROY PRODUCTS INTERNAL DUAL BEVERAGE HOLDER 4"	2 @ \$72.00	\$144.00	NEW
PART: FP-SGTRAY	TROY PRODUCTS 4" SHALLOW TRAY W/SLOPED FLOOR	1 @ \$56.25	\$56.25	NEW
PART: FP-BLNK1	TROY, 1" BLANK FILLER PLATE	2 @ \$14.63	\$29.26	NEW
PART: MAUNIAAWAMM	MAGNETIC MIC MOUNT	2 @ \$74.25	\$148.50	NEW
PART: CCRMMBTAPT	PERMANENT ANTENNA MOUNT, LAIRD MB8T - THICK ROOF 3/8"	1 @ \$70.88	\$70.88	NEW
PART: CCNMCOTAR8	BK ANNTENNA CONECTOR	1 @ \$25.65	\$25.65	NEW
PART: ANMRMRE21V	21IN NO TUNE ANTENNA	1 @ \$222.75	\$222.75	NEW
PART: FP-BKEM5992X	TROY, 3" FACE PLATE, FITS BENDIX KING EM5992X ONE-PIECE RADIO	1 @ \$56.25	\$56.25	NEW
PART: FP-KUSS-USB-3DC	TROY, 2" FACE PLATE, FITS 1X KUSSMAUL USB, 3X DC OUTLET HOLES	1 @ \$37.13	\$37.13	NEW
PART: 2975	80AMP RESETABLE CIRCUIT BREAKER	1 @ \$105.78	\$105.78	NEW
PART: 5026-BSS	FUSE BLOCK 12 CIRCUIT ST	1 @ \$86.57	\$86.57	NEW
PART: 1302724	STINGER LED RED	1 @ \$268.52	\$268.52	NEW
PART: 53732	NUTSERT-LARGE FLG, 8-32 UNC	25 @ \$1.11	\$27.75	NEW
PART: 33458	PH MACHINE SCREW, 8-32 X 3/4	25 @ \$0.75	\$18.75	NEW
PART: 42083	HEAT SHRINK ELECTRICAL CONNECTOR	15 @ \$2.04	\$30.60	NEW

Recommended Repairs:

Warranty: From the date of delivery for a period of 3 months or 3000 miles, whichever comes first, this firm will repair free of charge any defects in material and workmanship to the repairs stated on the invoice. All work to be done in our shop only. This does not include towing charges or customer supplied parts. A storage fee of 0.00 per day will be charged 24 hours after notification that work is complete. Neglect/abuse of vehicle will immediately void any and all warranties.

Labor/Jobs	\$4,050.00
Parts	\$2,392.66
Sublet	\$0.00
Total Fees	\$45.00
Subtotal	\$6,487.66
Tax @ 7.75%	\$185.43
Total	\$6,673.09
Payments	\$0.00
Balance	\$6,673.09

Replaced parts may be requested by customer. I hereby authorize the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I have read the above and acknowledge receipt of an estimate.

X _____ Date 1/15/2026

Elevated Mobile Repair, LLC.

1364 GRASSLAND ROAD
DAYTON, NV. 89403
(530) 329-6653



INVOICE # 1472

elevatedmobilerepair@gmail.com
elevatedmobilerepair.com
BAR# 3216900

INDEPENDENCE VOLUNTEER FIRE DEP	YEAR:	2020	/:	A/2X4
PO BOX B	MAKE/MODEL:	FREIGHTLINER WATER TEN	LICENSE/STATE:	1584026/CA
INDEPENDENCE, CA. 93526	VIN:	3ALACYFEXMDMP9011	MILES IN/MILES OUT:	13504/13504
Cell: (760) 920-1108 Work: (760) 878-2113	ENGINE:	CUMMINS L9	FLEET NUMBER	WT-2230

In: 5/28/2026 Out: 6/16/2026 Email: IVFDJOE@GMAIL.COM

VEHICLE ISSUE #1: REAR INTERSECTION LIGHTS				
TECH REPORT: CUSTOMER STATES THAT RIGHT INTERSECTION LIGHT IS BROKEN. REMOVED LIGHT AND INSTALLED NEW UPDATED VERSION ON LEFT AND RIGHT SIDES.				
PART: 60R02FRR	LIGHT, WHELEN 600 RED	2 @ \$256.20	\$512.40	NEW
PART: 6EFLANGE	WHELEN CHROME BEZEL	2 @ \$31.50	\$63.00	NEW
PART: SHIP12	SHIPPING	1 @ \$55.00	\$55.00	NEW
LABOR: TRAYLOR,	REPLACED LEFT AND RIGHT INTERSECTION LIGHTS	2 @ \$150.00	\$300.00	LABOR
			Total for "REAR INTERSECTION LIGHTS ": \$930.40	
			SHOP SUPPLIES : \$30.00	
			HAZARDOUS WASTE : \$30.00	

Recommended Repairs: Warranty: From the date of delivery for a period of 3 months or 3000 miles, whichever comes first, this firm will repair free of charge any defects in material and workmanship to the repairs stated on the invoice. All work to be done in our shop only. This does not include towing charges or customer supplied parts. A storage fee of 0.00 per day will be charged 24 hours after notification that work is complete. Neglect/abuse of vehicle will immediately void any and all warranties.	Labor/Jobs	\$300.00
	Parts	\$630.40
	Sublet	\$0.00
	Total Fees	\$60.00
	Subtotal	\$990.40
	Tax @ 7.75%	\$44.59
	Total	\$1,034.99
	Payments	\$0.00
	Balance	\$1,034.99

Replaced parts may be requested by customer. I hereby authorize the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I have read the above and acknowledge receipt of an estimate.

X _____ Date 6/16/2026

Wildland

Elevated Mobile Repair, LLC.

1364 GRASSLAND ROAD
DAYTON, NV. 89403
(530) 329-6653



INVOICE # 1485

elevatedmobilerepair@gmail.com
elevatedmobilerepair.com
BAR# 3216900

INDEPENDENCE VOLUNTEER FIRE DEP	YEAR:	2011	/:	A/4X4
PO BOX B	MAKE/MODEL:	FORD F-550	LICENSE/STATE:	1454538/CA
INDEPENDENCE, CA. 93526	VIN:	1FDOW5HT1BEB16030	MILES IN/MILES OUT:	22597/22597
Cell: (760) 920-1108 Work: (760) 878-2113	ENGINE:	6.7 POWERSTROKE	FLEET NUMBER	2228

In: 6/14/2026 Out: 6/16/2026 Email: IVFDJOE@GMAIL.COM

VEHICLE ISSUE #1: CHECK ENGINE LIGHT				
TECH REPORT: CUSTOMER STATES THAT CHECK ENGINE LIGHT IS ON. SCANNED VEHICLE FOR FAULT CODES AND FOUND CODE FOR EGT SENSOR 14 VOLTAGE BELOW NORMAL, WATCHED LIVE DATA OF ALL EGT SENSORS AND FOUND THAT SENSOR 14 WAS NOT WITHIN SPEC OF OTHERS CHECKED THAT POWER AND GROUND AT SENSOR WAS CORRECT. REMOVED AND REPLACED SENSOR AND CHECKED THAT LIVE DATA WAS CORRECT, CLEARED CODE AND TEST DROVE ENGINE LIGHT DID NOT COME ON.				
PART:	SENSOR, EGT	1 @ \$222.60	\$222.60	NEW
AC3Z-12B591-C				
LABOR:	TRAYLOR, DIAGNOSED AND REPLACED SENSOR	4 @ \$150.00	\$600.00	LABOR
		Total for "CHECK ENGINE LIGHT ": \$822.60		
VEHICLE ISSUE #2: BK RADIO NOT WORKING				
TECH REPORT: CUSTOMER STATES THAT BK RADIO IS BLACK AND WILL NOT TURN ON. CHECKED THAT POWER AND GROUND WERE CORRECT. UPDATED FIRMWARE TO LATEST VERSION. RADIO POWERED UP AND WORKED AS NORMAL.				
LABOR:	TRAYLOR, UPDATED BK RADIO FIRMWARE	1 @ \$150.00	\$150.00	LABOR
		Total for "BK RADIO NOT WORKING ": \$150.00		
		SHOP SUPPLIES : \$30.00		
		HAZARDOUS WASTE : \$30.00		

Recommended Repairs: Warranty: From the date of delivery for a period of 3 months or 3000 miles, whichever comes first, this firm will repair free of charge any defects in material and workmanship to the repairs stated on the invoice. All work to be done in our shop only. This does not include towing charges or customer supplied parts. A storage fee of 0.00 per day will be charged 24 hours after notification that work is complete. Neglect/abuse of vehicle will immediately void any and all warranties.	Labor/Jobs	\$750.00
	Parts	\$222.60
	Sublet	\$0.00
	Total Fees	\$60.00
	Subtotal	\$1,032.60
	Tax @ 7.75%	\$17.25
	Total	\$1,049.85
	Payments	\$0.00
	Balance	\$1,049.85

Replaced parts may be requested by customer. I hereby authorize the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I have read the above and acknowledge receipt of an estimate.

X _____ Date 6/16/2026

Wildland

Elevated Mobile Repair, LLC.

1364 GRASSLAND ROAD
DAYTON, NV. 89403
(530) 329-6653



INVOICE # 1487

elevatedmobilerepair@gmail.com
elevatedmobilerepair.com
BAR# 3216900

INDEPENDENCE VOLUNTEER FIRE DEP	YEAR:	2020	/:	A/2X4
PO BOX B	MAKE/MODEL:	FREIGHTLINER WATER TEN	LICENSE/STATE:	1584026/CA
INDEPENDENCE, CA. 93526	VIN:	3ALACYFEXMDMP9011	MILES IN/MILES OUT:	13504/13504
Cell: (760) 920-1108 Work: (760) 878-2113	ENGINE:	CUMMINS L9	FLEET NUMBER	WT-2230

In: 6/14/2026 Out: 6/16/2026 Email: IVFDJOE@GMAIL.COM

VEHICLE ISSUE #1: ANNUAL SERVICE

TECH REPORT: Changed engine oil and filter, replaced fuel filters, replaced engine air filter and cabin A/C filter. Greased chassis, checked pump gearbox oil, rear diff oil and all other fluids. Lubed discharge valve, push pull handles, cleaned windshield and topped off washer fluid. Blew out radiator, inspected belts, hoses, steering, brake system and drivetrain.

PART: P607960	FILTER, AIR	1 @ \$161.22	\$161.22	NEW
PART: R61709	FILTER, FUEL	1 @ \$91.49	\$91.49	NEW
PART: N10G36000006	FILTER, CABIN	1 @ \$26.38	\$26.38	NEW
PART: FF63054NN	FILTER, FUEL	1 @ \$94.55	\$94.55	NEW
PART: LF14009NN	FILTER, OIL	1 @ \$128.34	\$128.34	NEW
PART: SBDFTP-CA	15-40 SYN BLEND DIESEL OIL	22 @ \$12.50	\$275.00	NEW
LABOR: TRAYLOR,	PERFORMED ANNUAL SERVICE	4 @ \$150.00	\$600.00	LABOR

Total for "ANNUAL SERVICE ": \$1,376.98

SHOP SUPPLIES : \$30.00

HAZARDOUS WASTE : \$30.00

Recommended Repairs:

Warranty: From the date of delivery for a period of 3 months or 3000 miles, whichever comes first, this firm will repair free of charge any defects in material and workmanship to the repairs stated on the invoice. All work to be done in our shop only. This does not include towing charges or customer supplied parts. A storage fee of 0.00 per day will be charged 24 hours after notification that work is complete. Neglect/abuse of vehicle will immediately void any and all warranties.

Labor/Jobs	\$600.00
Parts	\$776.98
Sublet	\$0.00
Total Fees	\$60.00
Subtotal	\$1,436.98
Tax @ 7.75%	\$60.22
Total	\$1,497.20
Payments	\$0.00
Balance	\$1,497.20

Replaced parts may be requested by customer. I hereby authorize the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I have read the above and acknowledge receipt of an estimate.

X _____ Date 6/16/2026

Wildland

Elevated Mobile Repair, LLC.

1364 GRASSLAND ROAD
DAYTON, NV. 89403
(530) 329-6653



INVOICE # 1488

elevatedmobilerepair@gmail.com
elevatedmobilerepair.com
BAR# 3216900

INDEPENDENCE VOLUNTEER FIRE DEP	YEAR:	2011	/:	A/4X4
PO BOX B	MAKE/MODEL:	INTERNATIONAL 7400 TYP	LICENSE/STATE:	1250549/CA
INDEPENDENCE, CA. 93526	VIN:	1HTWEAZR0CJ688425	MILES IN/MILES OUT:	8476/8476
Cell: (760) 920-1108 Work: (760) 878-2113	ENGINE:	MAXXFORCE 10	FLEET NUMBER	E-2215

In: 6/14/2026 Out: 6/16/2026 Email: IVFDJOE@GMAIL.COM

VEHICLE ISSUE #1: ANNUAL SERVICE

TECH REPORT: Changed engine oil and filter, replaced fuel filter, checked engine air filter, checked cabin air filter. Greased chassis, checked pump gearbox oil, rear diff oil and all other fluids. Lubed discharge valve, push pull handles, cleaned windshield and topped off washer fluid. Blew out radiator, inspected belts, hoses, steering, brake system and drivetrain.

PART: SBDFTP-CA	15-40 SYN BLEND DIESEL OIL	33 @ \$12.50	\$412.50	NEW
PART: FS19947	FUEL FILTER	1 @ \$134.93	\$134.93	NEW
PART: LF17575	FILTER, OIL	1 @ \$108.15	\$108.15	NEW
PART: 2606467C92	FILTER SPINNER, OIL	1 @ \$88.38	\$88.38	NEW
PART: ZSH9404206021G	COOLANT	1 @ \$16.49	\$16.49	NEW
LABOR: TRAYLOR,	PERFORMED ANNUAL SERVICE	4 @ \$150.00	\$600.00	LABOR

Total for "ANNUAL SERVICE ": \$1,360.45

SHOP SUPPLIES : \$30.00

HAZARDOUS WASTE : \$30.00

Recommended Repairs:

Warranty: From the date of delivery for a period of 3 months or 3000 miles, whichever comes first, this firm will repair free of charge any defects in material and workmanship to the repairs stated on the invoice. All work to be done in our shop only. This does not include towing charges or customer supplied parts. A storage fee of 0.00 per day will be charged 24 hours after notification that work is complete. Neglect/abuse of vehicle will immediately void any and all warranties.

Labor/Jobs	\$600.00
Parts	\$760.45
Sublet	\$0.00
Total Fees	\$60.00
Subtotal	\$1,420.45
Tax @ 7.75%	\$58.93
Total	\$1,479.38
Payments	\$0.00
Balance	\$1,479.38

Replaced parts may be requested by customer. I hereby authorize the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I have read the above and acknowledge receipt of an estimate.

X _____ Date 6/16/2026

Wildant

Elevated Mobile Repair, LLC.

1364 GRASSLAND ROAD
DAYTON, NV. 89403
(530) 329-6653



INVOICE # 1486

elevatedmobilerepair@gmail.com
elevatedmobilerepair.com
BAR# 3216900

INDEPENDENCE VOLUNTEER FIRE DEP	YEAR:	2021	/:	A/2X4
PO BOX B	MAKE/MODEL:	FORD F-350	LICENSE/STATE:	1402592/CA
INDEPENDENCE, CA. 93526	VIN:	1FDRF3HT2MDA05507	MILES IN/MILES OUT:	18893/18893
Cell: (760) 920-1108 Work: (760) 878-2113	ENGINE:	6.7 POWERSTROKE	FLEET NUMBER	SIERRA 10

In: 6/14/2026 Out: 6/16/2026 Email: IVFDJOE@GMAIL.COM

VEHICLE ISSUE #1: CAB CLEARANCE LIGHT OUT			
TECH REPORT: CUSTOMER STATES THAT ONE CAB CLEARANCE LIGHT IS OUT. REMOVED AND REPLACED LIGHT ASSEMBLY. TESTED OK			
PART:	LAMP, CAB	1 @ \$129.82	\$129.82 NEW
HC3Z-15442-G			
LABOR: TRAYLOR,	REPLACED CAB CLEARANCE LIGHT	1 @ \$150.00	\$150.00 LABOR
		Total for "CAB CLEARANCE LIGHT OUT ": \$279.82	
		SHOP SUPPLIES : \$30.00	
		HAZARDOUS WASTE : \$30.00	

Recommended Repairs: Warranty: From the date of delivery for a period of 3 months or 3000 miles, whichever comes first, this firm will repair free of charge any defects in material and workmanship to the repairs stated on the invoice. All work to be done in our shop only. This does not include towing charges or customer supplied parts. A storage fee of 0.00 per day will be charged 24 hours after notification that work is complete. Neglect/abuse of vehicle will immediately void any and all warranties.	Labor/Jobs	\$150.00
	Parts	\$129.82
	Sublet	\$0.00
	Total Fees	\$60.00
	Subtotal	\$339.82
	Tax @ 7.75%	\$10.06
	Total	\$349.88
	Payments	\$0.00
	Balance	\$349.88

Replaced parts may be requested by customer. I hereby authorize the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I have read the above and acknowledge receipt of an estimate.

X _____ Date 6/16/2026

ambulance